

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Problem Image Mailbox.**

FIG 1

1 1/2 wall
 19' 3"
 ÷ 2
 9' 8"
 (2) 4' kictees
 7' 7"





FIG 2

BELLY DOOR CUT AWAY

- 1 BLOCK = 1"
- 1/4" PLATE STEEL
- 1/2" POLY BOARD
- 3" MC CHANNEL
- 3"x1" ANGLE IRON
- RUBBER SEAL



PLG 4

POLY FASTENER CUT AWAY





FIG 5 NOT TO SCALE






Fig. 6

ST. N. F. V. T. C. W.

1 BLOCK = 3"

8

8.5

23

3" CHAIR

3'

25

3' AUGER BECE

12

22

27

34

2.12"

0

0



20

Fig. 7

60

STEEL REINFORCEMENT

Fig. 8

STEEL REINFORCEMENT

65

65

ANGLE IRON
FRAME 66

Sq. TUBING
SUPPORTS 25

12
FLOOR OF CONTAINER

25

